



Product Change Notification / SYST-29TPZU587

Date:

02-Aug-2022

Product Category:

Ethernet Switches

PCN Type:

Document Change

Notification Subject:

Data Sheet - KSZ9563R 3-Port Gigabit Ethernet Switch with RGMII/MII/RMII Interface and IEEE 1588v2
- Data Sheet Revision

Affected CPNs:

[SYST-29TPZU587_Affected_CPN_08022022.pdf](#)
[SYST-29TPZU587_Affected_CPN_08022022.csv](#)

Notification Text:

SYST-29TPZU587

Microchip has released a new Datasheet for the KSZ9563R 3-Port Gigabit Ethernet Switch with RGMII/MII/RMII Interface and IEEE 1588v2 - Data Sheet of devices. If you are using one of these devices please read the document located at [KSZ9563R 3-Port Gigabit Ethernet Switch with RGMII/MII/RMII Interface and IEEE 1588v2 - Data Sheet](#).

Notification Status: Final

Description of Change: Revision includes:

Section 4.1.7, "Auto-Negotiation" Updated description from "mode" to "speed." Also added the following sentence: "With parallel detection, the duplex will always be half-duplex."

Section 4.1.7, "Auto-Negotiation" Updated description from "mode" to "speed." Also added the following sentence: "With parallel detection, the duplex will always be half-duplex."

Section 4.1.8, "LinkMD® Cable Diagnostics" Updated to add additional details and test script.

Section 4.11.1, "Media Independent Interface (MII)" Updated description to remove half duplex operation.

Section 5.1.2.2, "In-Band Management (IBA) Control Register" Added the following note to bit 31: "If using I2C, do not enable IBA."

-Section 5.1.3.2, "LED Strap-In Register" Changed definition from: "Strap-in values of Select RXD and LED pins [RXD2_1, RXD2_0, LED1_1, LED1_0]" to "Strap-in values of Select RXD and LED pins [RXD1, RXD0, LED1_1, LED1_0]".

Section 5.1.4.72, "Global PM Available Register" New register added for Packet Memory Available Block Count.

Section 5.1.5.3, "VLAN Table Entry 2 Register" Updated description of bits 2-0 from "1 = Untag packets upon egress at this port; 0 = Do not untag upon egress at this port" to "1 = Forward to this port; 0 = Do not forward to this port".

Section 5.1.6.1, "Global PTP Clock Control Register" Added the following note to bit 1: "The PTP Clock must be enabled when using the time stamp units (TSU) or trigger output units (TOU), even if IEEE 1588 is not implemented."

Section 5.1.6.21, "Trigger Output Unit Control 2 Register" Added the following note: "The minimum value for this parameter is 0x50."

Section 5.1.6.24, "Trigger Output Unit Control 5 Register" Removed the following advisory: "This register contains the PTP event trigger output PPS signal pulse width for unit 2 and path delay compensation for unit 1."

Section 5.2.2.1, "PHY Basic Control Register" Updated bit 7 from "Collision Test" to "Reserved".

Section 5.2.2.1, "PHY Basic Control Register" Updated bit 10 default value from "0b" to "1b".

Section 5.2.2.2, "PHY Basic Status Register" Updated bit 0 default from "0" to "1".

Section 5.2.2.4, "PHY ID Low Register" Updated value from "0x1631" to "0x1637".

Section 5.2.2.20, "PHY Auto MDI / MDI-X Register" Updated Reserved bit (15:8) default value from "0x00" to "0x24".

Section 5.2.2.21, "Port Special Register" Added register.

Section 5.2.7.4, "Port Authentication Control Register" Updated bit 2 definition from "1 = Enable; 0 = Enable" to "1 = Enable; 0 = Disable".

Section 5.2.9.2, "Port Control 1 Register" Updated address range from "0xNA04 - 0xNA03" to "0xNA04 - 0xNA07". Updated type from "RO" to "RW". Updated default value of bits 2-0 from "0b" to "1b". -

Section 5.2.9.3, "Port Transmit Queue Memory Register" Added register.

Section 5.4.1, "MMD LED Mode Register" Added the following text to bit 4: "For Single-LED mode, set this bit and also set bit 9 in register 0xN13C-0xN13D."

Table 5-7, "MMD Register Map" Updated example of MMD Register Read from: "Register 11h - 13h for the LED mode status" to "Register 00h for the MMD LED Mode Register."

Table 3-3, "Configuration Strap Descriptions" Added the following note to LED1_1: "If using I2C, do not enable IBA."

Table 4.8.5, "Energy Efficient Ethernet (EEE)" Corrected "disabled by default" to "enabled by default". Additionally, added the following sentence: "EEE is enabled or disabled in the MMD EEE Advertisement register."

Table 4-5, "Tail Tag Frame Format" Updated byte number for Tail Tagging from "2" to "1".

Table 3-2, "Pin Descriptions" For Power Management Event PME_N, updated buffer type from "IPU/O8" to "I/O8" and added the following note: "An external pull-up or pull-down resistor is required to set the desired strapping level."

Table 3-2, "Pin Descriptions" Updated pin RX_ER so that RMII mode is with MII mode.

Table 3-3, "Configuration Strap Descriptions" Updated RX_ER, PME_N description to remove "Default" from bit 1 and added the following note: "Note that PME_N does not have an internal pullup or pull-down, so an external pull-up or pull-down resistor is always required."

Table 6-12, "Power-up and Reset Timing Values" Updated Note 3 to indicate the following: "The power supplies may be powered down in any sequence."

Impacts to Data Sheet: See above details.

Reason for Change: To Improve Productivity

Change Implementation Status: Complete

Date Document Changes Effective: 2 August 2022

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachments:

[KSZ9563R 3-Port Gigabit Ethernet Switch with RGMII/MII/RMII Interface and IEEE 1588v2 - Data Sheet](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to receive Microchip PCNs via email please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to change your PCN profile, including opt out, please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Affected Catalog Part Numbers (CPN)

KSZ9563RNXC

KSZ9563RNXI

KSZ9563RNXC-TR

KSZ9563RNXI-TR