



CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M001074

DATE: 25-Apr-2022

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	DS28E40G/V+	N/A	25-Apr-2022	22-Oct-2022	Part can no longer be manufactured
Discontinuance	DS80C320-QNG+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	DS80C320-QNG+T&R	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	DS80C320-QNL+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	DS89C430-MNG+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	DS89C430-QNG+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	DS89C450-MNG+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX1098CEAE+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX1099CEAE+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX1298CEAE+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX1299CEAE+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX194BCPE+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX194BEPE+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX195BCPE+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX195BEPE+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX20076BATCB/VY+	MAX20076DATCB/VY+	25-Apr-2022	22-Oct-2022	Part can no longer be manufactured
Discontinuance	MAX20076BATCB/VY+T	MAX20076DATCB/VY+T	25-Apr-2022	22-Oct-2022	Part can no longer be manufactured
Discontinuance	MAX20480DB/VY+TCTF	MAX20480DATEB/VY+T	25-Apr-2022	22-Oct-2022	The part was not released
Discontinuance	MAX20480DC/VY+TCTF	MAX20480DATEC/VY+T	25-Apr-2022	22-Oct-2022	The part was not released
Discontinuance	MAX20480DD/VY+TCTF	MAX20480DATED/VY+T	25-Apr-2022	22-Oct-2022	The part was not released
Discontinuance	MAX20480DI/VY+TCTJ	MAX20480DATED/VY+T	25-Apr-2022	22-Oct-2022	The part was not released
Discontinuance	MAX4390EXT-T	MAX4390EXT+T	25-Apr-2022	22-Oct-2022	Part can no longer be manufactured
Discontinuance	MAX5033BUPA+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX5033CUPA+	MAX17501HATB+	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX5033DUPA+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX5035AUPA+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 26-May-2022

Discontinuance	MAX5035BUPA+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX5035CUPA+	MAX17502HAUD+	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX5035DUPA+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX504CPD+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX504EPD+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX5154BCPE+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX5158CPE+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX515CPA+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX531ACPD+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX531BCPD+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX531BEPD+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX5352ACPA+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX5352BCPA+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX5354CPA+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX5354EPA+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX535BCPA+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX538ACPA+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX538BCPA+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX538BEPA+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX539AEPA+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX539BCPA+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX539BEPA+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX547ACQH+D	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX547AEQH+D	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX547BCQH+D	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX547BCQH+TD	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX547BEQH+D	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX6225ACPA+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX6225BCPA+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX6225BEPA+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX6241ACPA+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX6241AEPA+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX6241BCPA+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX6241BEPA+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX6250ACPA+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX6250AEPA+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 26-May-2022

Discontinuance	MAX6250BCPA+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX6250BEPA+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX6302CPA+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX6302EPA+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX6303CPA+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX6303EPA+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX6325CPA+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX6325EPA+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX6341CPA+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX6341EPA+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX6350CPA+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX6350EPA+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX639CPA+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX639EPA+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX640CPA+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX674CPA+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX674EPA+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX675CPA+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX675EPA+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	MAX8596ZETA+T	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	REF01CP+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	REF01EP+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	REF01HP+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	REF02CP+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	REF02EP+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured
Discontinuance	REF02HP+	N/A	25-Apr-2023	22-Oct-2023	Part can no longer be manufactured