

# End of Life Notification

From time to time we find it necessary to change, modify, or replace our product offering. These changes are usually the result of advancements in technology that offer improvements in performance or manufacturability. Unavailability of component parts, generally of an earlier technology or an older design, can cause the obsolescence of outdated product families.

We sincerely appreciate your business and will make every effort to work with you during your transition to the new power supplies. In some cases of obsolescence, a new advanced model has been introduced to replace the existing power supplies. All products now being discontinued are available for an end-of-life last time buy.

We have recommended a suitable replacement for your convenience on most of the end-of-life models. If you have any questions or need specific application assistance, please contact us (you may visit <https://www.artesyn.com/contact>, Email to [productsupport.ep@Artesyn.com](mailto:productsupport.ep@Artesyn.com) or call 1-888-412-7832) or your local sales representative to assist you. Thank you for your continued patronage.

The following models have been marked as EOL:

Model No	Replacement Model	Replacement Info	LTB start	LTB end
DS1050-3		There is no direct replacement for this model. Recommended CSU1300AP-3-600 as a close alternative.	07/08/2020	12/31/2020
DS1050-3-002		There is no direct replacement for this model. Recommended CSU1300AP-3-600 as a close alternative.	07/08/2020	12/31/2020
DS650-9-002		There is no direct replacement for this model.	07/08/2020	12/31/2020
DS850-9-002		There is no direct replacement for this model.	07/08/2020	12/31/2020
DSR1050-0		There is no direct replacement for this model.	07/08/2020	12/31/2020
ATCR250-48D12-03J		There is no replacement model available or planned for the ATCR250	06/30/2022	10/30/2020