




Product Change Notice: P4S Series Connectors

PCN.PGC10.12.12.2017

12.12.2017

| <p>About This Notice:</p> | <p>To improve product reliability, Panasonic will be changing the plating specification for P4S Series Header Side Connectors to a Nickel barrier construction to better protect against solder rise.</p> | | | | | | |
|--|--|---------------|--------------|--|--|--|--|
| <p>Effective Date:</p> | <p>March 1, 2018</p> | | | | | | |
| <p>Change Details:</p> | <p>What is Ni barrier construction?</p> <div data-bbox="552 882 1494 1165" data-label="Diagram"> <p>Cross sectional view of A-A</p> </div> <ul style="list-style-type: none"> * Depending on the product type, the lower part of the V notch may assume the Ni color. This will not affect contact reliability. * In previous products, the socket already has the Ni barrier. <p>Label Change</p> <table border="1" data-bbox="479 1344 1477 1722"> <thead> <tr> <th data-bbox="479 1344 974 1386">Before change</th> <th data-bbox="977 1344 1477 1386">After change</th> </tr> </thead> <tbody> <tr> <td data-bbox="479 1390 974 1564"> </td> <td data-bbox="977 1390 1477 1564"> </td> </tr> <tr> <td colspan="2" data-bbox="479 1568 1477 1722"> <p>Temporarily during the changeover period, a ● mark will be displayed above the quantity on the inner and outer labels of the changed product. This will continue for six months until the end of August 2018. The ● mark will not be displayed from September onward.</p> </td> </tr> </tbody> </table> | Before change | After change | | | <p>Temporarily during the changeover period, a ● mark will be displayed above the quantity on the inner and outer labels of the changed product. This will continue for six months until the end of August 2018. The ● mark will not be displayed from September onward.</p> | |
| Before change | After change | | | | | | |
| | | | | | | | |
| <p>Temporarily during the changeover period, a ● mark will be displayed above the quantity on the inner and outer labels of the changed product. This will continue for six months until the end of August 2018. The ● mark will not be displayed from September onward.</p> | | | | | | | |



na.industrial.panasonic.com

industrial@us.panasonic.com

1-800-344-2112

Affected Parts: See attached.

Datasheet(s): See attached.

Notes: Please note that part numbers, pricing and specifications will remain unchanged.

Manufacturer Part Number

AXT440124
AXT320224
AXT360224
AXT410124
AXT316124
AXT430124
AXT340224
AXT334124
AXT340124
AXT330224
AXT324124
AXT330124
AXT332124
AXT460124
AXT430224
AXT480124
AXT310124
AXT416124
AXT320124
AXT434124
AXT444124
AXT450124
AXT420324
AXT354124
AXT350124
AXT380224
AXT300224
AXT344124
AXT310124A
AXT410124A
AXT320124A
AXT420124A
AXT324124A
AXT424124A
AXT330124A
AXT430124A
AXT334124A
AXT434124A
AXT340124A
AXT440124A
AXT420124
AXT326124
AXT432124
AXT346124
AXT424124
AXT4E1026

AXT310154
AXT410114
AXT322124
AXT422124
AXT426124
AXT336124
AXT436124
AXT316154
AXT338124
AXT416114
AXT438124
AXT446124
AXT320154
AXT420114
AXT454124
AXT422114
AXT360124
AXT364124
AXT464124
AXT324154
AXT424114
AXT322154
AXT420354
AXT470124
AXT380124
AXT426114
AXT370124
AXT390124
AXT490124
AXT330154
AXT330254
AXT430114
AXT430314
AXT332154
AXT432114
AXT300124
AXT400124
AXT334154
AXT434114
AXT326154
AXT434164
AXT336154
AXT436114
AXT338154
AXT438114
AXT340154
AXT440114

AXT344154
AXT444114
AXT350154
AXT450114
AXT430324
AXT354154
AXT454114
AXT350164
AXT460114
AXT3501F4
AXT4E1066
AXT360154
AXT440224
AXT3E1026
AXT370154
AXT470114
AXT3501F4A
AXT380154
AXT380254
AXT380264
AXT480114
AXT480314
AXT480324
AXT310114
AXT320214
AXT320254
AXT322114
AXT330214
AXT332114
AXT410154
AXT416154
AXT420154
AXT420314
AXT422154
AXT424154
AXT426154
AXT430154
AXT430354
AXT430364
AXT432154
AXT434154
AXT436154
AXT438154
AXT440154
AXT444154
AXT446114
AXT316114

AXT320114
AXT324114
AXT326114
AXT330114
AXT334114
AXT336114
AXT338114
AXT340114
AXT3E2026
AXT3E2066
AXT390154
AXT490114
AXT4E5066
AXT300154
AXT400114
AXT3E5066
AXT400224
AXT360214
AXT360254
AXT380214
AXT400154
AXT400314
AXT400324
AXT450154
AXT450164
AXT454154
AXT460154
AXT460314
AXT460324
AXT470154
AXT480154
AXT480354
AXT480364
AXT490154
AXT344114
AXT346114
AXT350114
AXT354114
AXT360114
AXT370114
AXT380114
AXT390114
AXT300114
AXT300164
AXT320164
AXT322164
AXT326164

AXT328124
AXT328154
AXT328164
AXT330164
AXT330264
AXT336164
AXT338164
AXT340164
AXT342224
AXT344164
AXT354164
AXT356124
AXT356154
AXT356164
AXT356214
AXT356224
AXT356254
AXT356264
AXT360164
AXT360264
AXT370164
AXT380164
AXT390164
AXT3A2224
AXT3A2254
AXT3A2264
AXT400164
AXT416164
AXT420164
AXT422164
AXT426164
AXT428114
AXT428124
AXT428154
AXT428164
AXT430164
AXT432164
AXT436164
AXT438164
AXT442314
AXT442324
AXT444164
AXT454164
AXT456114
AXT456124
AXT456154
AXT456164

AXT456314
AXT456324
AXT460164
AXT470164
AXT480164
AXT490164
AXT4A2314
AXT310164
AXT316164
AXT320264
AXT334164
AXT410164
AXT324164
AXT332164
AXT424164
AXT440164
AXT4E2026
AXT340264