



# Product Change Notice

PCN Number: 16-1149-01  
Issue Date: 04-APRIL-2017

Exar Corporation

[www.exar.com](http://www.exar.com) | Support: [customersupport@exar.com](mailto:customersupport@exar.com)

<b>PRODUCTS AFFECTED:</b>	XRT5997IVTR-F	SP510EEF-L	SP508ECF-L	XRT73L02MIV-F
	XRT5997IV-F	SP3508CF-L	SP508EEF-L	XRT75L02IV-F
	SP510ECF-L	SP3508EF-L		

**CHANGE CATEGORY:**

<input type="checkbox"/> Material	<input type="checkbox"/> Process	<input type="checkbox"/> Package
<input type="checkbox"/> Design	<input type="checkbox"/> Datasheet	<input type="checkbox"/> Packing/Shipping
<input checked="" type="checkbox"/> Other: Alternate Site		

**DESCRIPTION OF CHANGE:**  
Qualification of alternate assembly subcon, Greatek, Taiwan.

**IMPACT OF CHANGE:**  
There is no change to product form, fit or function.

**TARGET IMPLEMENTATION DATE:** 04-JULY-2017

Please contact customer support ([customersupport@exar.com](mailto:customersupport@exar.com)) for sample date availability or qualification data

**PROPRIETARY INFORMATION**  
THIS DOCUMENT CONTAINS INFORMATION WHICH IS THE EXCLUSIVE PROPERTY OF EXAR CORPORATION. DISTRIBUTION, REPRODUCTION OR USE BY OTHERS IS NOT PERMITTED WITHOUT THE EXPRESS WRITTEN AUTHORIZATION OF EXAR CORPORATION.