



End of Life Notification for Vishay Siliconix PDIP18, PDIP20 and PDIP28 Analog Switch ICs

DESCRIPTION OF CHANGE: Vishay Siliconix announces the end of life of Plastic DIP Packages 18, 20 and 28 Pins Analog Switches

CLASSIFICATION OF CHANGE: Product Obsolescence

REASON FOR CHANGE: Obsolescence of Assembly

EXPECTED INFLUENCE ON PERFORMANCE/QUALITY/RELIABILITY: N/A

PRODUCT CATEGORY: ICs

PART NUMBERS AFFECTED:

Part Number	Package	Recommended Replacement	Recommended Part Package
DG428DJ-E3	PDIP18	DG428DN-E3	PLCC20
DG429DJ-E3	PDIP18	DG429DN-E3	PLCC20
DG333ADJ-E3	PDIP20	DG333ADQ-T1-E3	TSSOP20
DG333ALDJ-E3	PDIP20	DG333ALDQ-T1-E3	TSSOP20
DG406BDJ-E3	PDIP28	DG406BDN-E3	PLCC28
DG406DJ-E3	PDIP28	DG406BDN-E3	PLCC28
DG407BDJ-E3	PDIP28	DG407BDN-E3	PLCC28
DG407DJ-E3	PDIP28	DG407BDN-E3	PLCC28

VISHAY BRAND(s): Vishay-Siliconix

TIME SCHEDULE: Immediately. There are no more assembly site available.

This PTN is for notification purposes only. Your response is not required. If you have any questions, please contact your local Vishay Sales Office.

ISSUED BY: Isabelle Ciacchella, Vishay Siliconix IC Product Marketing.
E-mail address: isabelle.ciacchella@vishay.com

For further information, please contact your regional Vishay office.

The Americas
Vishay Americas
2201 Laurelwood Road
Santa Clara, Ca 95004
T: 408-970-8000
F: 408-567-8942
business-americas@vishay.com

Europe
Vishay Electronic GmbH
Geheimrat-Rosenthal-Strasse 100
D-95100
Selb, Germany
T: 49-9287-71 0
F: 49-9287-70435
Europe@vishay.com

Asia
Vishay Intertechnology Asia Pte. Ltd
25 Tampines Street 92
#02-00 Keppel Building
Singapore 528877
T: 65-6788-6668
F: 65-6788-0988
business-asia@vishay.com