



Product Discontinuance Notice - PDN 15_0005 Rev. -

Analog Devices, Inc. Three Technology Way Norwood, Massachusetts 02062-9106

This notice is to inform you of a product discontinuance for certain ADI products (see Discontinued Parts Material List below). Any issues with this PDN must be sent to ADI as soon as possible. The information contained within this PDN is considered proprietary and should not be shared outside of your company. ADI contact information is listed below.

PDN Title:

Obsolescence of ADSP-BF535 Blackfin Processors

Publication Date: 30-Jan-2015

Last Time Buy Date: 30-Jan-2016

Last Time Ship Date: 30-Jan-2017

Revision Description:

Initial Release

Reason For Discontinuance

Discontinuing these ADSP-BF535 products due to decreased customer demand.

Supporting Documents None

For questions on this PDN, send email to the regional contacts below or contact your local ADI sales representative

Americas: PDN_Americas@analog.com

Europe: PDN_Europe@analog.com

Japan: PDN_Japan@analog.com

Rest of Asia: PDN_ROA@analog.com

PDN 15_0005 Discontinued Parts Material List

Model	Product Family	Replacement Part	Pin To Pin Compatible	Comments
ADSP-BF535PBB-200	ADSP-BF535	ADSP-BF536BBCZ-4A	No	
ADSP-BF535PBB-300	ADSP-BF535	ADSP-BF536BBCZ-4A	No	
ADSP-BF535PBBZ-200	ADSP-BF535	ADSP-BF536BBCZ-4A	No	
ADSP-BF535PKB-300	ADSP-BF535	ADSP-BF536BBCZ-4A	No	
ADSP-BF535PKB-350	ADSP-BF535	ADSP-BF536BBCZ-4A	No	
ADSP-BF535PKBZ-300	ADSP-BF535	ADSP-BF536BBCZ-4A	No	
ADSP-BF535PKBZ-350	ADSP-BF535	ADSP-BF536BBCZ-4A	No	

Appendix A - PDN 15_0005 Revision History

Rev	Publish Date	Rev Description
Rev. -	30-Jan-2015	Initial Release

Analog Devices, Inc. Proprietary Information

DocId:850 Layout Rev:2 Parent DocId:None