



# Product Change Notice

PCN Number: 16-0521-04  
Issue Date: 2-DECEMBER-2016

Exar Corporation

[www.exar.com](http://www.exar.com) | Support: [customersupport@exar.com](mailto:customersupport@exar.com)

**PRODUCTS AFFECTED:**

SP6213EC5-L-3-3/TR	SP6201EM5-L/TR	SP6201EM5-L-1-5/TR	SP6201EM5-L-1-8/TR
SP6201EM5-L-2-5/TR	SP6213EC5-L-3-0/TR	SP6201EM5-L-3-0/TR	SP6201EM5-L-3-3/TR
SP6201EM5-L-5-0/TR	SP6213EC5-L-1-8/TR	SP6213EC5-L-2-5/TR	

**CHANGE CATEGORY:**

- |  |                                    |   |
|--|------------------------------------|---|
| <input type="checkbox"/> Material                                    | <input type="checkbox"/> Process   | <input type="checkbox"/> Package          |
| <input type="checkbox"/> Design                                      | <input type="checkbox"/> Datasheet | <input type="checkbox"/> Packing/Shipping |
| <input checked="" type="checkbox"/> Other: Alternate assembly subcon |                                    |   |

**DESCRIPTION OF CHANGE:**

Qualification of alternate assembly subcon, JCET.

**IMPACT OF CHANGE:**

There is no change to product form, fit or function.

**TARGET IMPLEMENTATION DATE:** 2-MARCH-2017

Please contact customer support ([customersupport@exar.com](mailto:customersupport@exar.com)) for sample date availability or qualification data

**PROPRIETARY INFORMATION**

THIS DOCUMENT CONTAINS INFORMATION WHICH IS THE EXCLUSIVE PROPERTY OF EXAR CORPORATION. DISTRIBUTION, REPRODUCTION OR USE BY OTHERS IS NOT PERMITTED WITHOUT THE EXPRESS WRITTEN AUTHORIZATION OF EXAR CORPORATION.