

Product Discontinuation



PD_168_19

■ Last Order Date:	2020-06-30
■ Last Delivery Date:	2021-06-30

Reason: Introduction of Gen 2 package

DISCONTINUED				NEW (REPLACEMENT)			
Sales Name	SP Number	OPN	Package	Sales Name	SP Number	OPN	Package
BTF6070-2EKV	SP001208316	BTF60702EKVXUMA1	PG-DSO-14	BTF6070-2ERV	SP001682636	BTF60702ERVXUMA1	PG-TDSO-14
BTT6010-1EKA	SP001054658	BTT60101EKAXUMA1	PG-DSO-14	BTT6010-1ERA	SP001682640	BTT60101ERAXUMA1	PG-TDSO-14
BTT6010-1EKB	SP001279034	BTT60101EKBXUMA1	PG-DSO-14	BTT6010-1ERB	SP001682644	BTT60101ERBXUMA1	PG-TDSO-14
BTT6020-1EKA	SP001004942	BTT60201EKAXUMA1	PG-DSO-14	BTT6020-1ERA	SP001682648	BTT60201ERAXUMA1	PG-TDSO-14
BTT6030-1EKA	SP001004944	BTT60301EKAXUMA1	PG-DSO-14	BTT6030-1ERA	SP001682652	BTT60301ERAXUMA1	PG-TDSO-14
BTT6030-2EKA	SP001004946	BTT60302EKAXUMA1	PG-DSO-14	BTT6030-2ERA	SP001682656	BTT60302ERAXUMA1	PG-TDSO-14
BTT6030-2EKB	SP001364296	BTT60302EKBXUMA1	PG-DSO-14	BTT6030-2ERB	SP001682660	BTT60302ERBXUMA1	PG-TDSO-14
BTT6050-1EKA	SP001004948	BTT60501EKAXUMA1	PG-DSO-14	BTT6050-1ERA	SP001682664	BTT60501ERAXUMA1	PG-TDSO-14
BTT6050-2EKA	SP000866750	BTT60502EKAXUMA1	PG-DSO-14	BTT6050-2ERA	SP001682668	BTT60502ERAXUMA1	PG-TDSO-14
BTT6100-2EKA	SP001070124	BTT61002EKAXUMA1	PG-DSO-14	BTT6100-2ERA	SP001682672	BTT61002ERAXUMA1	PG-TDSO-14
BTT6200-1EJA	SP001070122	BTT62001EJAXUMA1	PG-DSO-8	BTT6200-1ENA	SP001597296	BTT62001ENAXUMA1	PG-TDSO-8
BTT6200-4EMA	SP001070118	BTT62004EMAXUMA1	PG-SSOP-24	BTT6200-4ESA	SP002479018	BTT62004ESAXUMA1	PG-TSDSO-24

If you have any questions, please do not hesitate to contact your local sales office.

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended! If Infineon confirms a purchase order with a delivery date beyond last delivery date, the PD with the mentioned last ordering date still remains valid.