

Product Change Notice

Issue Date: 22-December-2022

Change Description:

Introduction of replacement die for below part numbers.

Parts Affected:

Refer to appendix.

Description and Extent of Change:

The new die will replace the existing die for all affected part numbers. The new die is qualified per Broadcom's qualification process.

Reasons for Change:

Obsolescence of existing die.

Effect of Change on Fit, Form, Function, Quality, or Reliability:

There is no change in fit, form, function, quality and reliability.

Effective Date of Change:

Effective 27-Jan-2023.

Shipment may contains parts from existing die and new die starting 27-Jan-2023 until the inventory of existing die is fully depleted.

Qualification Data:

Qualification data will be provided upon request.

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements. Please acknowledge the receipt of the notice within 30 days of delivery. Lack of acknowledgement within 30 days constitutes acceptance of the change per JEDEC J-STD-046.

Appendix:

Part number list:

HSMF-C113	HSMR-C130-00001	QSMN-C124	QSMR-R13A
HSMF-C114	HSMR-C150	QSMN-C185	QSMW-B123
HSMF-C115	HSMR-C170	QSMN-C194	QSMW-B193
HSMF-C118	HSMR-C190	QSMN-C199	QSMW-C12C
HSMF-C146	HSMR-C191	QSMR-C12D	QSMW-C12E
HSMF-C164	HSMR-C197	QSMR-C12E	QSMW-C12H
HSMF-C169	HSMR-C265	QSMR-C130-QRBC0	QSMW-C197-QRBD0
HSMF-C179	HSMR-C280	QSMR-C153	QSMW-C19M
HSMF-C186	HSMR-C380	QSMR-C175	QSMW-C19N
HSMF-C187	HSMW-B191	QSMR-C197-MNAD0	QSMW-C19P
HSMF-C189	HSMW-C120	QSMR-C19B	QSMW-C19T
HSMF-C12E	HSMW-C130	QSMR-C19J	QSMW-C270
HSMF-C2A1	HSMW-C170	QSMR-C19M	QSMW-C271
HSMN-C110	HSMW-C191	QSMR-C19N	QSMW-C273
HSMN-C120	HSMW-C265	QSMR-C19V	QSMW-C275
HSMN-C150	HSMW-C280	QSMR-C19W	QSMW-R13S
HSMN-C170	HSMW-C340	QSMR-C262	QSMW-Z130-00002
HSMN-C190	QSMF-C11H	QSMR-C264	ASMT-FG70-NFJ00
HSMN-C191	QSMF-C11K	QSMR-C351	QSMT-FG71-NFJ00
HSMR-C110	QSMF-C11Q	QSMR-C381	
HSMR-C120	QSMF-C11S	QSMR-C681	
HSMR-C130	QSMF-C120	QSMR-E190-PQBC0	